ROUTING AND	TRANSMITTAL SLIP	Date	
		3/23/83	7
O: (Name, office symbouilding, Agency/Po	ol, room number, ost)	Initials Date	
11/10	2/0/-	1/01/3/24	
. 0/23-		1001 191	1
. 80	•	M 3/2	A STATE OF THE STA
200	· · · · · · · · · · · · · · · · · · ·	10	703
ADD A		24 MAR 19	100
DOA		7	
-			
EXDII	7_		
Action	File	Note and Return	and the second s
Approval	- For Clearance	Per Conversation	-
As Requested	For Correction	Prepare Reply	
Circulate	For Your Information		
Comment	Investigate	Signature	. •
Coordination EMARKS	Justify		-
NOT use this form	as a RECORD of approva clearances, and similar act	ls, concurrences, disposals, ons	- 1 1 1 1 1 1 1 1.
			-
		Phone No.	Herose 1811
	0570	M FORM 41 (D-:: 7 70)	
GPO : 1980 O ~ 311-156	Prescribe FPMR (4:	AL FORM 41 (Rev. 7-76) d by GSA i CFR) 101-11.206	
	.*		
			0.7 13 15 15 15 15 15 15 15 15 15 15 15 15 15
			ILL
			·

	3-23-83	
	DD/A Reg	istr
MEMORANDUM FOR	R: Chief, Logistics Services Division 83-09	3
FROM	Chief, Motor Pool Branch, LSD/OL	
SUBJECT	: Executive Deputy Director's Assigned Vehicle Tire Replacement	
Per your	telephone call regarding the rough ride in	
assigned vehic	cle, the following action was taken by the maintenance section:	
	-Mechanics, road tested the vehicle with driver. They found that the vehicle had a very little vibration at a speed at approximately 65 m.p.h. -After rebalancing the tires on the front and rear, the car was tested at 65 m.p.h. speed. and	
	stated that no vibration was experienced. the chauffeur assigned to subject vehicle stated to me after balancing was completed that he had driven the vehicle to and it rode o.k.	
I asked h	nim, if he was satisfied with the ride and he said yes. Mr.	
was furt	ther advised to report to the Maintenance Section, immediately	
anytime that h	ne sensed or experienced that something is wrong with the	
vehicle.		

Approved For Release 2008/05/19 : CIA-RDP85B01152R000600770041-5

25X1

25X1

25X1

25X1

25X1

25X1 25X1

25X1

25X1

2011